



---

# HT-EM4

## Release Notes

[1.0.6]

---

# hitron

Date: [2022-07-26]

## Notice

---

This document contains information, which is the proprietary property of Hitron Technologies, Inc. This document is received in confidence and its contents cannot be disclosed or copied without the prior written consent of Hitron Technologies, Inc.

Nothing in this document constitutes a guarantee, warranty, or license, express or implied. Hitron Technologies, Inc. disclaims all liability for all such guarantees, warranties, and licenses, including but not limited to: fitness for a particular purpose; merchantability; non-infringement of intellectual property or other rights of any third party or of Hitron Technologies, Inc.; indemnity; and all others. The reader is advised that third parties can have intellectual property rights that can be relevant to this document and the technologies discussed herein and is advised to seek the advice of competent legal counsel.

## Copyright

Copyright © Hitron Technologies, Inc. 2022. All rights reserved.

## Trademarks

This document may contain registered trademarks of Hitron Technologies, Inc.

\*Other product and corporate names may be trademarks of other companies and are used only for explanation and to the owners' benefit, without intent to infringe.

# Table of Contents

---

2	Overview .....	4
3	Important Notes .....	4
4	Fixes & Enhancements .....	4
5	Known Issues & Future Enhancements .....	4
6	Release Details & Supporting Documentation .....	5
7	Release History .....	5



## 2 Overview

This document contains the following:

Section	Content
2	Important notes
3	Fixes & enhancements found in current software revision as well as previous ones
4	Known issues and features still in development
5	Release details and additional supporting documentation
6	Release history

## 3 Important Notes

It is necessary to add a MoCA filter when using MOCA connection, the filters purpose is to BLOCK MoCA network generated data streams from exiting the subscriber's dwell and interfering with other neighborhood MoCA networks.

## 4 Fixes & Enhancements

ID	Summary	Fixed Version	Resolution Summary
HTM4AE-35	Add option to change username and password for login in next release.	1.0.6	GUI has support modify password
HTM4AE-36	Reject DHCP Public IP Address and force to static if public DHCP address is offered.	1.0.6	Generate an ipmg with static ip by default or modify it to static ip in the network settings of the GUI
HTM4AE-37	Add phy rates GUI	1.0.6	Has support PHY Rate page in GUI

## 5 Known Issues & Future Enhancements

Hitron wants to communicate this subset of tickets still open in their JIRA system. This is not an all-inclusive summary.

ID	Summary	Severity

## 6 Release Details & Supporting Documentation

Documentation is only updated when there is an actual need for a change, not for every software version by default. In the case that an older document version is listed below, that older version is still current for this particular release. Please contact Hitron Support to obtain any of the documents listed below, if required.

Document	Version
Bootloader Version:	MXL37xx_MOCA_HOSTLESS_BOOT_LOADER.bin
Software Version:	1.0.6
image name:	HT-EM4-1.0.6b2.bin
MD5 of image:	8499be8a8aad9cefd41d888ac128b27b (dhcp ip) 125a49c4ecd663b65dd7250046bb4785 (static ip)
MoCA Driver Version:	v1.18.10

## 7 Release History

Version	Release Date
1.0.6	2022-07-26
1.0.6	2022-07-18
1.0.5	2021-01-22
1.0.4	2019-12-18
1.0.3	2019-11-26
1.0.2	2019-05-06
1.0.1	2019-02-22